

S.Y. Diploma : Sem. III
Electrical Engineering
 [EJ/EN/ET/EX/DE/IS/IC/IE/EV/MU]
 MSBTE Prelim Question Paper Solution

Time: 3 Hrs.]

[Marks : 100

Q.1 Attempt any TEN of the following. [20]

Q.1(a) State E.M.F. equation of transformer and write meaning of each term in the formula. [2]

(A) E.M. F. equation of transformer:

$$E_1 = 4.44 f \phi_{\max} N_1 \quad \text{OR} \quad E_1 = 4.44 B_{\max} N_1 A$$

$$E_2 = 4.44 f \phi_{\max} N_2 \quad \text{OR} \quad E_2 = 4.44 B_{\max} N_2 A$$

where

N_1 = number of turns in primary

N_2 = number of turns in secondary

ϕ_{\max} = maximum flux in core in weber

B_{\max} = maximum flux density in core in Wb/m^2

A = core area in $(\text{meter})^2$

E_1 = R.M.S. value of induced emf in primary


E_2 = R.M.S. value of induced emf in secondary

Q.1(b) Why should a transformer be never connected to DC supply. [2]

(A) With DC supply (of value equal to AC rated voltage) the transformer winding will draw current equal to V_{dc}/R . The winding resistance R being low and XL being absent for DC, the current I_{dc} would be vary large and transformer will fail within few seconds by overheating of windings. Due to this reason, transformer should never be operated on DC supply.

Q.1(c) Draw the voltage waveform of three phase AC supply for 0 to 2π . [2]

(A)



Q.1(d) List the various losses that occur in a transformer. [2]

(A) The various losses that occur in a transformer:

- (i) Copper losses
- (ii) Core or Iron losses:
 - (a) Hysteresis loss
 - (b) Eddy current loss

Q.1(e) State the Faraday's law of electromagnetic induction. [2]

(A) Faraday's first law of electromagnetic induction:

When a conductor cuts or is cut by the magnetic flux, an EMF is generated in the conductor.

Faraday's second law of electromagnetic induction:

The magnitude of EMF induced in the coil depends on rate of change of flux linking with coil.

Q.1(f) Define RMS value and Average value of an electrical quantity. [2]

(A) (i) Average value

The average value I_{av} of an alternating current is expressed by that steady i.e. direct current which transfers across any circuit the same charge as is transferred by that alternating current during the same time.

In the case of sinusoidal wave form, Average value is given by

$$I_{av} = \frac{2I_m}{\pi} = 0.637 I_m$$

R.M.S., Effective or Virtual value

The r.m.s value of an alternating current is given by the steady (d.c.) current which when flowing through a given circuit for a given time produces the same heat as produced by the alternating current when flowing through the same circuit for the same time.

The equation of the alternating current varying sinusoidally is given by :

$$i = I_m \sin\theta$$

$$I_{RMS} = \frac{I_m}{\sqrt{2}} = 0.707 I_m$$

Q.1(g) State the expansion of the terms : (i) MCCB (ii) ELCB. [2]


- (A)**
- (i) MCCB = Moulded Case Circuit Breaker
 - (ii) ELCB = Earth Leakage Circuit Breakers

Q.1(h) Define phase sequence in 3 phase a.c. supply. [2]

(A) Phase sequence

The order in which the voltages in the three phases reach their max. +ve values (or any other specific instantaneous value) is called the phase sequence or phase order. It is determined by the direction of rotation of the alternator.

Thus in the Figure, the phase sequence can be written as $R \rightarrow Y \rightarrow B$ since the coil rotate anticlockwise, however, for the clockwise rotation it can be written as $R \rightarrow B \rightarrow Y$.



Q.1(i) State the types of earthing. [2]

(A) Types of earthing:

- Plate earthing.
- Pipe earthing.
- Earth mat (mesh of metal strips) for huge power installations as generating stations etc.

Q.1(j) Write the equation of V and I in pure capacitive circuit. [2]

(A) Equation of voltage

$$v = V_m \sin \omega t \quad \text{OR} \quad V_m \sin \phi$$

Equation current

$$i = I_m \sin (\omega t + \pi/2)$$

$$i = I_m \sin (\phi + \pi/2)$$

$$i = I_m \sin (\omega t + 90^\circ)$$

$$i = I_m \sin (\phi + 90^\circ)$$

Q.1(k) List speed control methods for three phase I.M. [2]

(A) Speed control methods for three phase I.M.

- (i) By changing the number of stator poles (P) (pole changing)
- (ii) By changing the line frequency (Frequency control)
- (iii) By changing the applied voltage (stator voltage control)
- (iv) By changing resistance in the rotor circuit (Rotor resistance control)
- (v) By voltage /frequency (V/F) control method

Q.1(I) List two applications of universal motor. [2]

(A) Application of Universal Motor:

- | | |
|---|-------------------------|
| (i) Mixer | (ii) Food processor |
| (iii) Heavy duty machine tools | (iv) Grinder |
| (v) Vacuum cleaners | (vi) Refrigerators |
| (vii) Driving sewing machines | (viii) Electric Shavers |
| (ix) Hair dryers | (x) Small Fans |
| (xi) Cloth washing machine | |
| (xii) Portable tools like blowers, drilling machine, polishers etc. | |

Q.2 Attempt any FOUR of the following : [16]

Q.2(a) What are the advantages of three-phase system over single-phase system? [4]

(A) Advantages of three-phase system over single-phase system

- In Three Phase System, two voltages i.e. line voltage and Phase Voltage are available but in Single Phase only one Voltage is available.
- Motors working on Three Phase are Self-Starting, where as Motors working on 1-Phase are not self starting.
- For the same capacity, three phase machine occupies less space than 1-phase machine.
- for the same capacity, three phase machine is lighter than 1-phase machine.
- 3-phase transmission line is more efficient and requires less copper than 1-phase.

Q.2(b) An alternating current given by equation $i = 142.14 \sin 628t$. Find: [4]

- | | |
|-----------------|--------------------|
| (i) RMS value | (ii) Average value |
| (iii) Frequency | (iv) Time period |

(A) Given equation, $i = 142.14 \sin 628t$

(1) RMS value

$$I = I_m \sin \omega t$$

$$\therefore I_m = 142.14, \omega = 628$$

$$I_{rms} = \frac{I_m}{\sqrt{2}} = \frac{142.14}{\sqrt{2}} = 100.523 \text{ A}$$

(2) Average value

$$I_{av} = \frac{2I_m}{\pi} = 0.637 I_m = 90.543 \text{ A}$$

(3) Frequency

$$\omega = 2\pi f$$

$$\therefore f = \frac{\omega}{2\pi} = \frac{628}{2\pi} = 100 \text{ cycles/sec.}$$


(4) Time period

$$T = \frac{1}{f} = \frac{1}{100} = 0.01 \text{ sec.}$$


Q.2(c) With the help of waveforms and phasor diagrams show the phase relationship between voltage and current in pure inductive and pure capacitive circuits. [4]

(A) Pure inductance circuit :

Waveform



Phase Diagram




(i) Equation for voltage $V = V_m \sin \omega t$


(ii) Equation for current $I = I_m \sin (\omega t - \pi/2)$ or $I_m \sin (\omega t - 90^\circ)$

Pure capacitive circuit:

Waveform



Phase Diagram



(i) Equation for voltage = $V = V_m \sin \omega t$

(ii) Equation for current = $I = I_m \sin \omega t + \pi/2$ or $I_m \sin (\omega t + 90^\circ)$

Q.2(d) Compare core type and shell type single phase transformer (any four points). [4]

(A)

	Core Type Transformer	Shell Type Transformer
(i)	The Winding surround the core.	The core surround the windings.
(ii)	Magnetic Flux has only one continuous path.	Magnetic Flux is distributed into 2 paths.
(iii)	Suitable for high voltage & less output.	Suitable for less voltage & high output.
(iv)	Easy for repairs.	Difficult for repairs.
(v)	Less in Weight.	More in Weight.
(vi)	It has one window opening.	It has two windows opening.

Q.2(e) Balanced star connected load supplied from three phase 415 V, 50 Hz system, current in each phase is $20 \angle -30^\circ$, 30° being w.r.t. phase voltage. Determine :

(i) V_{ph} (ii) I_L (iii) $\cos \phi$ (iv) Power

(A) (i) In star connection, $V_{ph} = \frac{V_L}{\sqrt{3}} = \frac{415}{\sqrt{3}}$
 $V_{ph} = 239.6$ volts

(ii) In star connection, $I_{ph} = I_L$
 $I_{ph} = 20 \angle -30^\circ$ A

(iii) $\cos \phi = \cos (-30^\circ) = 0.866$

(iv) Power

$$P = 3V_{ph} I_{ph} \cos \phi$$

$$= 3 \times 239.6 \times 20 \times 0.866$$

$$= 124490616 \text{ watts}$$

OR

$$P = \sqrt{3} V_L I_L \cos \phi$$

$$= \sqrt{3} \times 415 \times 20 \times 0.866$$


$$= 124490616 \text{ watts}$$

Q.3 Attempt any FOUR of the following : [16]

Q.3(a) The coil having a resistance of 10Ω and an inductance of 0.2 Henry is connected to a 100 V, 50 Hz supply. Calculate : [4]

- (i) the impedance of the coil
- (ii) the reactance of the coil.
- (iii) the current drawn and
- (iv) the phase difference between the current and the applied voltage

- (A) Given : $R = 10 \Omega$
 $H = 0.2 \text{ H}$
 $100 \text{ V, } 50 \text{ Hz supply}$
 $\omega = 2\pi f$
 $= 2\pi \times 50 = 100 \pi \text{ rad/sec}$



- (i) impedance of coil, $z = R + j X_L$
 $z = 10 + j 62.83 \Omega$
 $z_{\text{coil}} = 63.62 \angle 80.95 \Omega$

- (ii) Reactance of coil $= X_L = \omega L$
 $= (2\pi f) \times L$
 $= (100 \pi) \times 0.2 \Omega = 20 \pi$
 $X_L = 62.83 \Omega$

- (iii) Current drawn $= I = \frac{V}{z} = \frac{100 \text{ V}}{63.62 \angle 80.95} = 1.571 \angle -80.95$
 \therefore current drawn is $= 1.571 \text{ A}$

- (iv) the phase difference between the current and the applied voltage
 i.e. angle of impedance (ϕ)
 $\therefore \phi = 80.95^\circ$

Q.3(b) Explain the difference between statically induced emf. and [4]
 dynamically induced emf.


(A)

	Dynamically induced emf	Statically induced emf
(i)	The emf induced by the change in the flux linking with the coil by its motion relative to a magnetic field is called dynamically induced emf.	The emf induced by the change in the flux linking with the coil without resort to its motion relative to a magnetic field is called statically induced emf.
(ii)	The magnitude of dynamically induced emf is given as $e = B \ell v \sin \theta$ volts where, $B =$ Flux density $\ell =$ Active length $v =$ Velocity (m/s) $\theta =$ Angle made by the conductor with the direction of magnetic flux.	The magnitude of statically induced emf is given as $e = -N \frac{d\phi}{dt}$ volts where, $N =$ Number of turns in the coil $\phi =$ magnetic flux

(iii)	Example, Electrical generators	Example, Choke coil in fluorescent tube, filter circuit of a rectifier.
(iv)	Dynamic emf is a motion of electrons so the emf is dynamic.	Static emf is no motion of electron.


Q.3(c) Draw a R-L-C series circuit and phasor diagram. Also write [4] equations.

(A) R-L-C Series circuit with phasor diagram



Phasor Diagram: (Any one phasor diagram expected)

(i) $X_L > X_C$ (lagging) (ii) $X_C > X_L$ (leading) (iii) $X_L = X_C$ (UPF)



Equations for R-L-C series circuit :

$$X_C = \frac{1}{2\pi fC}$$

$$X_L = 2\pi fL$$

$$\text{Impedance } Z = \sqrt{(R)^2 + (X_L - X_C)^2}$$

$$I = \frac{V}{Z}$$

$$\cos \phi = \frac{R}{Z}$$

For $X_C > X_L$:

- (i) Equation for voltage $V = V_m \sin \omega t$
- (ii) Equation for current $I = I_m \sin (\omega t + \phi)$

For $X_C < X_L$:

- (i) Equation for voltage $V = V_m \sin \omega t$
- (ii) Equation for current $I = I_m \sin (\omega t - \phi)$

For $X_L = X_C$:

- (i) Equation for voltage $V = V_m \sin \omega t$
- (ii) Equation for current $I = I_m \sin \omega t$

Q.3(d) What are the different types of power in AC circuit? State its formula. [4]

(A) (i) Active power (P)

It is the true power or real power in a ac circuit given by the product of voltage and active component of the current. It is given by formula $P = VI \cos \phi$ watt or kW or MW.

(ii) Reactive power (Q)

It is the product of voltage and reactive component of current. It is given by $Q = VI \sin \phi$ volt-amp-reactive or kVAR or MVAR.

(iii) Apparent power (S)

It is the product of rms value of voltage and current. It is given by formula. $S = VI$ volt-amp or kVA or MVA.

Q.3(e) Why transformer rating in terms of KVA not in kW? [4]

(A) (i) The output of transformer is limited by heating and by the losses. Two types of losses in the transformer: (1) Iron loss, (2) Copper loss

(ii) Iron loss depends on the transformer voltage (v) Copper loss is depends on transformer current (I).


(iii) As the losses depends on voltage (V) and Current (I) and almost unaffected by load power factor.

Hence transformer output is expressed in VA or KVA not in KW.

Q.4 Attempt any FOUR of the following : [16]

Q.4(a) Draw and explain torque-speed characteristics of 3-phase I.M. [4]

(A) Torque-Speed characteristics



Speed-Torque Curve for a Three-Phase Induction Motor

Explanation: From the above characteristics:

- When Slip (S) $\cong 0$ (i.e $N \cong N_s$) torque is almost zero at no load, hence characteristics start from origin.
- As load on motor increases Slip increases and therefore torques increases.
- For lower values of load, torque proportional to slip, and characteristics will having linear nature.
- At a particular value of Slip, maximum torque conditions will be obtained which is $R_2 = SX_2$.
- For higher values of load i.e. for higher values of slip, torque inversely proportional to slip and characteristics will having hyperbolic nature. In short breakdown occurs due to over load.
- The maximum torque condition can be obtained at any required slip by changing rotor resistance.

Q.4(b) Compare auto-transformer and two winding transformer. (any four [4] points)

(A)

	Points	Autotransformer	Two winding transformer
(1)	Symbol		
(2)	Number of windings	It has one winding.	It has two windings.
(3)	Copper saving	Copper saving takes more as compared to two winding.	Copper saving is less.

(4)	Size	Size is small.	Size is large.
(5)	Cost	Cost is low.	Cost is high.
(6)	Losses in winding	Less losses takes place.	More losses takes place.
(7)	Efficiency	Efficiency is high.	Efficiency is low.
(8)	Regulation	Regulation is better.	Regulation is poor.
(9)	Electrical isolation	There is no electrical isolation.	Electrical isolation is present in between primary and secondary winding.
(10)	Movable contact	Movable contact is present.	Movable contact is not present.
(11)	Application	Variac, starting of ac motors, dimmerstat.	Mains transformer, power supply, welding, isolation transformer.

Q.4(c) Define : (i) Slip (ii) Rotor frequency (iii) Synchronous (iv) Slip speed [4]

(A) (i) Slip

The difference between synchronous speed and actual speed of the rotor expressed as fraction or percentage of synchronous speed, is called slip.

$$\% s = \frac{(N_s - N)}{N_s} \times 100$$

(ii) Rotor frequency

The frequency of rotor emf is proportional to relative speed ($N_s - N$) of rotating stator field with respect to the rotor. It is given by

$$f_r = \text{slip} \times \text{supply frequency} = s.f$$

(iii) Synchronous speed

The speed of rotating magnetic field produced by stator winding is called as synchronous speed. It is given by

$$N_s = 120 \frac{f}{p}$$

(iv) Slip speed

The relative speed between rotor and rotating magnetic field is called as slip-speed. It is given by ($N_s - N$).


Q.4(d) Compare three phase squirrel cage induction motor and slip ring induction motor based on starting torque, starting current, power factor and maintenance cost. [4]

(A)

Parameters	Squirrel cage I.M.	Slip ring Slip ring I.M.
starting torque	Low	High with rotor resistance starter.
starting current	More	Less
power factor	Better running	Better starting
maintenance cost	Less	More

Q.4(e) State the principle of operation of an universal motor. Give any two applications. [4]

(A) Operating principle is the interaction of the main field and field due to current in the armature conductors to produce force/torque for motion. The force is directly proportional to the product of main flux and armature current.



Applications

- vacuum cleaners
- food mixers
- domestic sewing machine
- drill machine
- blenders
- hair dryers etc.

Q.5 Attempt any FOUR of the following : [16]

Q.5(a) A single phase transformer has 350 primary and 1050 secondary turns. The net cross-sectional area of core is 55 cm². If primary winding is connected to a 400 V, 50 Hz, 1-phase supply. Calculate. [4]

- (i) Maximum value of flux density in the core.
- (ii) Voltage induced in the secondary.

(A) Given data : $N_1 = 350, N_2 = 1050, a = 55 \text{ cm}^2 = 55 \times 10^{-4} \text{ m}^2$.
 $B_m = ?$ and $V_1 = ?$

$$E_1 = 4.44 * f * \phi_m * N_1$$

$$400 = 4.44 * 50 * \phi_m * 350$$

$$\phi_m = 0.005148 \text{ Wb}$$

$$B_m = \phi_m / a$$

$$= 0.005148 / 55 * 10^{-4}$$

$$B_m = 0.936 \text{ wb/m}^2$$

Transformation ratio (k) = $V_2 / V_1 = N_2 / N_1$

$$V_2 = (N_2 / N_1) * V_1$$

$$V_2 = 1050 / 350 * 400$$

$$V_2 = 1200 \text{ VOLTS}$$

Q.5(b) Three identical coils each of impedances $(4.2 + j5.6)\Omega$ are [4] connected in delta across 415 V, 50 Hz three phase power supply.

Determine :

- (i) V_{ph} (ii) I_{ph}
 (iii) Power factor (iv) Power absorbed by each coil

(A) Given : $Z_{ph} = (4.2 + j 5.6)\Omega$, $V_L = 415 \text{ V}$, $f = 50 \text{ Hz}$, Delta connection

(i) To find V_{ph} :

In delta connection $V_{ph} = V_L$
 Hence, $V_{ph} = V_L = 415 \text{ V}$

(ii) To find I_{ph} :

$$I_{ph} = \frac{V_{ph}}{Z_{ph}}$$

$$I_{ph} = \frac{415 \angle 0^\circ}{4.2 + j 5.6}$$

$$I_{ph} = \frac{415 \angle 0^\circ}{7 \angle 53.13^\circ}$$

$$I_{ph} = 59.28 \angle - 53.13^\circ \text{ Amp}$$

(iii) To find $\cos \phi$:

$$\cos \phi = \cos (- 53.13)$$

$$= 0.6$$

OR

$$\cos \phi = \frac{R}{Z}$$

$$\cos \phi = \frac{4.2}{7} = 0.6$$

(iv) To find power consumed by each coil

$$\text{Power consumed by each coil} = V_{ph} I_{ph} \cos \phi = 415 \times 59.28 \times 0.6$$

$$= 14760.72 \text{ watt} = 14.7607 \text{ kW}$$

Q.5(c) A resistance of 10 ohm, inductance of 0.1 H and capacitance of 100 microfarad are connected in series across 100 volts, 50 Hz, AC supply. Find : [4]

(i) Current

(ii) Power factor

(iii) Power

(iv) Draw phasor diagram.

(A)

$$I = \frac{V}{Z}$$

$$X_L = 2\pi fL = 2\pi \times 50 \times 0.1$$

$$X_L = 31.4159 \Omega$$

$$X_C = \frac{1}{2\pi fC} = \frac{1}{2\pi \times 50 \times 100 \times 10^{-6}}$$

$$X_C = 31.8309 \Omega$$

$$\text{Impedance } Z = \sqrt{(R)^2 (X_L - X_C)^2}$$

$$\text{Impedance } Z = \sqrt{(10)^2 + (31.4159 - 31.8309)^2}$$

$$\text{Impedance } Z = 10.0035 \text{ ohm}$$

(i) To find current

$$I = \frac{V}{Z} = \frac{100}{10.0035}$$

$$I = 9.9964 \text{ Amp}$$

(ii) To Power Factor

$$\cos \phi = \frac{R}{Z} = \frac{10}{10.0035}$$

$$\cos \phi = 0.9996$$


(iii) Power

$$P = V I \cos \phi$$

$$P = 100 \times 10 \times 0.9996$$

$$P = 999.6426 \text{ Watt}$$

(iv) Phasor diagram



Q.5(d) A 100 kVA, single phase transformer has a full load Cu loss of 3 kW and iron loss of 2 kW. Find the efficiency of the transformer at half and full load at unity power factor. [4]

(A) Efficiency at half load

$$\eta_{HL} = \frac{\frac{1}{2} \times \text{kVA} \times \cos \phi}{\frac{1}{2} \times \text{kVA} \times \cos \phi + \text{Iron losses} + \left(\frac{1}{2}\right)^2 \text{ copper losses}} \times 100$$

$$\eta_{HL} = \frac{\frac{1}{2} \times 100 \times 1}{\frac{1}{2} \times 100 \times 1 + 2 + 0.75} \times 100$$

$$\eta_{HL} = 94.79\%$$

Efficiency at Full Load


$$\eta_{FLL} = \frac{\text{kVA} \times \cos \phi}{\text{kVA} \times \cos \phi + \text{Iron losses} + \text{copper losses}} \times 100$$

$$\eta_{FLL} = \frac{100 \times 1}{100 \times 1 + 2 + 3} \times 100$$

$$\eta_{FLL} = 95.23\%$$

Q.5(e) Draw the schematic representation and state the principle of working of split phase single phase induction motor. [4]

(A)



Working of resistors split single phase induction motor:

- (i) In resistors split phase I.M. shown in above figure 'a', the main winding has low resistance but high reactance whereas the starting winding has a high resistance, but low reactance.
- (ii) The resistance of the starting winding may be increased either by connecting a high resistance 'R' in series with it or by choosing a high-resistance fine copper wire for winding purpose.

(iii) A centrifugal switch S is connected in series with the starting winding and is located inside the motor.

Its function is to automatically disconnect the starting winding from the supply when the motor has reached 70 to 80 per cent of its full load speed.

Q.6 Attempt any FOUR of the following : [16]

Q.6(a) Write four applications of stepper motor. [4]

(A) Applications of stepper motor:

- (1) Suitable for use with computer controlled system.
- (2) Widely used in numerical control of machine tools.
- (3) Tape drives
- (4) Floppy disc drives
- (5) Computer printers
- (6) X-Y plotters
- (7) Robotics
- (8) Textile industries
- (9) Integrated circuit fabrication
- (10) Electric watches
- (11) In space craft's launched for scientific explorations of planets.
- (12) In the production of science fiction movies
- (13) Automotive
- (14) Food processing
- (15) Packaging

Q.6(b) Define fuse. State the necessity of fuse. Write rating of fuses used in labs and mention the classification of fuses. [4]

(A) Fuse: a fuse is a short piece of metal, inserted in the circuit, which melts when excessive current flows through it and thus breaks the circuit.

Necessity of fuse:

- It provides short circuit protection.
- It provides overload protection.

Rating of fuses: 2 A, 3 A, 5 A, 6A, 10 A, 16 A etc.

Classification of fuse:

Low voltage fuses-

- Semi-enclosed rewirable fuse
- High rupturing capacity (HRC) cartridge fuse.
- HRC fuse with tripping device
- High voltage fuse
- Cartridge type fuse
- Liquid type fuse
- Metal clad fuse


Q.6(c) State specifications and two applications of isolation transformer [4] and radio-frequency transformer.

(A)

	Isolation Transformer	Radio frequency transformer
Specifications	Power rating 0.125,0.25, 0.5,..., phase, frequency: 47 - 50 Hz.	Frequency in MHz, Power rating, voltage, current etc.
Applications	1. Areas where common mode noise is generated.	1. To transfer rf signal from one circuit to another circuit
	2. Protect sensitive equipment from unwanted voltage spikes on primary side.	2. Impedance matching to achieve maximum power transfer and to suppress undesired signal reflection.
	3. Used in electronic circuits for isolation.	3. Voltage, current step-up or step-down.
	4. Used in circuits to avoid audio and video distortions.	4. DC isolation between circuits while affording efficient AC transmission

Q.6(d) Draw and explain working of megger. [4]

(A) Diagram of Megger:




Working of Megger:

- The voltage for testing is supplied by a hand generator incorporated in the instrument or by battery or electronic voltage charger. It is usually 250V or 500V and is smaller in size.
- A test volt of 500V D.C is suitable for testing ship's equipment operating at 440V A.C. Test voltage of 1000V to 5000V is used onboard for high voltage system onboard.
- The current carrying coil (deflecting coil) is connected in series and carries the current taken by the circuit under test. The pressure coil (control coil) is connected across the circuit.

- Current limiting resistor - CCR and PCR are connected in series with pressure and current coil to prevent damage in case of low resistance in external source.
- In hand generator, the armature is moving in the field of permanent magnet or vice versa, to generate a test voltage by electromagnetic induction effect.
- With an increase of potential voltage across the external circuit, the deflection of the pointer increases; and with an increase of current, the deflection of pointer decrease so the resultant torque on the movement is directly proportional to the potential difference and inversely proportional to the resistance.
- When the external circuit is open, torque due to voltage coil will be maximum and the pointer will read "infinity". When there is short circuit the pointer will read "0".

Q.6(e) Draw the schematic representation and state the principle of [4]
working of servo motor.

(A) Schematic representation :



Principle of working of servo motor:

There are some special types of application of electrical motor where rotation of the motor is required for just a certain angle not continuously for long period of time. For these applications some special types of motor are required with some special arrangement which makes the motor to rotate a certain angle for a given electrical input (signal). Such motors can be ac or dc motors. When controlled by servo mechanisms are termed as servomotors.

These consist of main and control winding and squirrel cage / drag cup type rotors. V_r is the voltage applied to the main or reference winding while V_c is that applied to control winding which controls the torque- speed

characteristics. The 90° space displacement of the two coils/windings and the 90° phase difference between the voltages applied to them result in production of rotating magnetic field in the air gap due to which the rotor is set in motion. The power signals can be fed from servo amplifiers either to the field or armature depending upon the required characteristics.

OR

Working of AC Servomotor:

- The control Phase is usually supplied from a servo amplifier.
- The speed and torque of the rotor are controlled by the phase difference between the control voltage and the reference phase voltage.
- The direction of rotation of the rotor can be reversed by reversing the phase difference, from leading to lagging (or vice versa) between the control phase voltage and the reference phase voltage.

□ □ □ □ □